

BMW Group - AIR: 2017-12-15 / 10:35
Retailer: 42868/01
Model: X5 xDrive30d
Vehicle identification number: 0C38979
Development code: F15
Model code: KS41
Lead type: KS41
Order number: -

Vehicle

BMW X5 xDrive30d, 190KW
0C38979



Development code	F15
Colour	IMPERIAL BLUE BRILLANT EFFECT
Actual integration level	F025-16-11-502
Start of warranty	04 March 2014

Technical campaigns

There are no Technical Campaigns for this vehicle.

Service contracts

Please check DCSnet Warranty Vehicle Inquiry in DCSnet for available service contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Next 2014-1 (As of: 24-Nov-2016)	No valid subscription available.	-	Road Map EUROPE Next 2018-1

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	X5 xDrive30d
Body	GEFZG
Vehicle identification number	0C38979
Vehicle identification number (17-digits)	WBAKS410100C38979
Development code	F15

Steering	LL
Engine	N57T
Engine number	30948719
Transmission	AUT
Transmission number	0321518WTR
Head unit serial number	HB2068F3133606
Drive	ALLR
Integration level, works	F025-13-11-504
Production date	07-Jan-2014
Delivery date	04-Feb-2014
National-market version	EUR
Paint number	A89
Upholstery code	NAEX
Model code	KS41
Basic type	KS41

Optional equipment

Optional equipment ex works:

01CB CO2 CONTENT
0217 ACTIVE STEERING
0230 EU SPECIFIC ADDITIONAL EQUIPMENT
0233 INCREASED TOWING CAPACITY
0258 RUNFLAT TYRES
02AZ 18"LT/ALY WHEELS DOUBLE SP. 446
02TB SPORT AUTOMATIC TRANSMISSION
0322 COMFORT ACCESS SYSTEM
0328 ALUMINIUM RUNNING BOARD SILL
03AC TRAILER TOW HITCH
03AT ROOF RAILS ALUMINIUM SATINATED
03E2 EXTERIEURDESIGN PURE EXPERIENCE
03MB INDIVIDUAL EXT.LINE ALU. SATINATED
0402 PANORAMA GLASS ROOF
0413 LUGGAGE COMPARTMENT NET
0423 FLOOR MATS, VELOUR
0428 WARNING TRIANGLE
0430 INTERIOR AND EXTERIOR MIRROR PACKA
0456 COMFORT SEATS, ELECTRIC. ADJUSTABLE
0488 LUMBAR SUPPORT DRIVER/FRONT PASSENGER
0494 SEAT HEATING F DRIVER/FRONT PASSENGER
04CV FINE-WOOD TRIM AMERICAN OAK
0502 HEADLIGHT WASHER SYSTEM
0508 PARK DISTANCE CONTROL (PDC)
0522 XENON LIGHT
0524 ADAPTIVE HEADLIGHTS
0534 AUTOMATIC AIR CONDITIONING
0536 AUXILIARY HEATING
0548 SPEEDOMETER WITH KILOMETER READING
0563 LIGHTS PACKAGE
0575 ADDITIONAL 12V POWER SOCKET
05A1 LED-FOG LIGHTS
05AC AUTOM. HIGH-BEAM HEADLIGHTS CONTROL
05DA PASSENGER AIRBAG DEACTIVATE
05DF ACTIVE CRUISE CTRL+STOP&GO FUNCT.
0609 NAVIGATION SYSTEM PROFESSIONAL
0610 HEAD UP DISPLAY

Retrofitted optional equipment:

This vehicle has no retrofits.

15/12/2017	AIR - Vehicle
0698 AREA-CODE 2 06AC INTELLIGENT EMERGENCY CALL 06AE TELESERVICES 06AK CONNECTEDDRIVE SERVICES 06AM REAL TIME TRAFFIC INFORMATION 06AN CONCIERGE SERVICES 06AP REMOTE SERVICES 06NR APPS 06NS ENHANCED TELEPHONY WITH EXTENDED SM 0710 M LEATHER STEERING WHEEL 07S5 INTERIEUR DESIGN PURE EXCELLENCE 07XP NAVIGATION PACKAGE CONNECTEDDRIVE 0801 GERMANY VERSION 0851 LANGUAGE VERSION GERMAN 0879 GERMAN / ON-BOARD DOCUMENTATION 08KA OELSERVICE INT. 30.000 KM/24 MONTHS 08TF ACTIVE PROTECTION FOR PEDESTRIANS 08TH SPEED LIMIT INFO 08V1 NCAP LABEL 0925 SHIPPING PROTECTION PACKAGE LEDE Leather equipment A105 AGM battery, 105 Ah works	

Encodable retrofittings

i **Note:** Please check with ISTA/P if additional further encodable retrofittings are possible.

Possible retrofitting:

Conversion, oil service interval 18 months/15000 km/10000 mi
Conversion, alternative frequency tracing activating
Conversion, oil service interval 24 months/12000 km/8000 mi
Conversion deactivate Comfort Access via K-Word
Conversion, ConnectedShift deactivation
Retrofit, 90 Ah battery
Retrofit, rear view camera
Retrofit, 90 Ah AGM battery
Conversion, deactivate front passenger seat belt warning
Retrofit, 70 Ah battery
Backfitting electrical articulating trailer tow hitch
Conversion, deactivate driver seat belt warning
Retrofit, 80 Ah battery
Conversion Sport brake installation
Conversion, opening of rear lid only possible after unlocking
Retrofit, anti-theft alarm system
Retrofit, 70 Ah AGM battery
Conversion, oil service interval 12 months/12000 km/8000 mi
Retrofit, DVD changer
Retrofit, Performance Control
Conversion, 3./4. function key (FFB) for the tailgate release
Conversion, response characteristics brake in wet conditions, strong
Conversion, setting threshold value for rain/light sensor to insensitive
Conversion, oil service interval 12 months/8000 km/5000 mi
Retrofit, 80 Ah AGM battery
Conversion, setting threshold value for rain/light sensor to sensitive
Retrofit, iPhone Station
Conversion, deactivate convenience opening
Conversion, oil service interval 12 months/15000 km/10000 mi

Potentially possible retrofitting (please check with ISTA-P):

Conversion, deactivate Telematics
Conversion, deactivate daytime driving lights
Retrofitting multifunctional instrument display
Conversion, ICM replacement
Retrofit Diesel Performance
Conversion of OE poor fuel grade

Service History

Service date	Vehicle mileage	Retailer	Manual
09/06/16	145555 km	07825 Autohaus Reier GmbH&Co. KG, Oranienburg	No

<https://myair-b2d-us.bmwgroup.com/air/faces/xhtml/fahrzeug/FahrzeugSingleView.xhtml?vin=0C38979>

									
-2600		-2600	-2600		17000		01/2017	60000	-2600
✓		✓	✓						03/2017

04/01/16

114760 km

07825 Autohaus Reier GmbH&Co. KG, Oranienburg

No

									
3600	3600	3600	3600	-1100		01/2017	60000	33000	
✓	✓	✓	✓	✓			✓		03/2017

08/09/15

88673 km

07825 Autohaus Reier GmbH & Co. KG, Oranienburg

No

									
900		900	900		5000		01/2017	5000	900
✓		✓	✓					✓	03/2017

16/02/15

59568 km

07825 Autohaus Reier GmbH & Co. KG, Oranienburg

No

									
110	110	110	110		21000		01/2017	19000	110
✓	✓	✓	✓					✓	03/2017

18/08/14

29047 km

07825 Autohaus Reier GmbH & Co. KG, Oranienburg

No

									
1200		1200	1200		45000		01/2017	40000	34000
✓		✓	✓						03/2017

Key history (KeyReader)

Date when key wa... Vehicle mileage Retailer Key number

22/12/16 175137 km 07825 0

									
-30	-30	-30	-30		5000		0	37000	26000
06/2018	554	554	554		10/2020			06/2020	03/2017

08/11/16 169934 km 07825 0

									
4500	4500	4500	4500		5000		0	42000	29000
06/2018	598	598	598		10/2020			06/2020	03/2017

06/10/16 167920 km 07825 0

										
8000	8000	8000	8000	8000	5000	0	43000	38000	0	
06/2018	637	637	637	637	01/2017			06/2020	03/2017	

09/06/16

145555 km

07825

0

										
-2600	0	-2600	-2600	0	17000	0	60000	-2600	0	
01/2018		600	600		01/2017			01/2018	03/2017	

12/04/16

133997 km

07825

0

										
9000	0	9000	9000	0	9000	0	70000	9000	0	
01/2018		659	659		01/2017			01/2018	03/2017	

29/03/16

131338 km

07825

0

										
11000	0	11000	11000	0	11000	0	70000	11000	0	
01/2018		672	672		01/2017			01/2018	03/2017	

12/02/16

122756 km

07825

0

										
21000	0	21000	21000	0	19000	0	80000	21000	0	
01/2018		718	718		01/2017			01/2018	03/2017	

04/01/16

114763 km

07825

0

										
3600	3600	3600	3600	-1100	0	60000	33000	0		
09/2017	635	635	635	01/2017			09/2019	03/2017		

04/01/16

114760 km

07825

0

										
3600	3600	3600	3600	-1100	0	60000	33000	0		
09/2017	635	635	635	01/2017			09/2019	03/2017		

16/10/15

94859 km

07825

0

										
25000	25000	25000	25000	80000	0	80000	60000	0		
09/2017	714	714	714	01/2017			09/2019	03/2017		

08/09/15

88673 km

07825

0

										
900	0	900	900	0	5000	0	5000	900	0	
02/2017		539	539		01/2017			02/2017	03/2017	

07/08/15

82826 km

07825

0

									
8000	0	8000	8000	0	5000	0	5000	8000	0
02/2017		571	571		01/2017			02/2017	03/2017

17/04/15

67828 km

07825

0

									
22000	0	22000	22000	0	13000	0	11000	22000	0
02/2017		683	683		01/2017			02/2017	03/2017

26/02/15

61018 km

07825

0

									
29000	0	29000	29000	0	19000	0	18000	29000	0
02/2017		733	733		01/2017			02/2017	03/2017

16/02/15

59568 km

07825

0

									
110	110	110	110	110	21000	0	19000	110	0
08/2016	562	562	562	562	01/2017			08/2016	03/2017

26/01/15

56917 km

07825

0

									
2800	2800	2800	2800	2800	23000	0	21000	2800	0
08/2016	582	582	582	582	01/2017			08/2016	03/2017

03/11/14

43504 km

07825

0

									
18000	18000	18000	18000	18000	35000	0	32000	18000	0
08/2016	667	667	667	667	01/2017			08/2016	03/2017

18/08/14

29047 km

07825

0

									
1200	0	1200	1200	0	45000	0	40000	34000	0
01/2016		530	530		01/2017			01/2018	03/2017

24/02/14

5 km

07825

0

There is no additional information available for this entry.

Warranty history

Date of repair Vehicle mileage Retailer

12/04/16 19240 km 07825

Job: Front axle brakes - cyclical vibration from steering wheel Poor running characteristics / friction

Description

Front axle brakes - cyclical vibration from steering wheel Poor running characteristics / friction

Job time without allowance for / brakes
Flat rate unit | 34 99 000

Perform brake test on test stand
Flat rate unit | 34 00 009

Removing and installing or replacing both front brake discs
Flat rate unit | 34 11 220

Balancing front and rear wheels stationary
Flat rate unit | 36 10 568

Removing and installing or replacing both front brake discs
Flat rate unit | 34 11 609

Repair kit, brake pads asbestos-free 1.0
Part | 34 11 6 852 253

Wheel bolt black 1.0
Part | 36 13 6 781 151

Brake disc, ventilated 2.0
Part | 34 11 6 868 939

16/02/16 8013 km 07825

Job: Front axle brakes - cyclical vibration from steering wheel Poor running characteristics / friction

Description Front axle brakes - cyclical vibration from steering wheel Poor running characteristics / friction

Removing and installing or replacing both front brake discs
Flat rate unit | 34 11 609

Perform brake test on test stand
Flat rate unit | 34 00 009

Inner hex bolt 2.0
Part | 34 21 1 161 806

Brake disc, ventilated 2.0
Part | 34 11 6 868 939

Repair kit, brake pads asbestos-free 1.0
Part | 34 11 6 852 253

Brake pad wear sensor, front left 1.0
Part | 34 35 6 792 567

16/02/15 59568 km 07825

Job: SCR transfer lines, including filters/metering line, including heater Cracked / broken / torn off

Description SCR transfer lines, including filters/metering line, including heater
Cracked / broken / torn off

Performing vehicle test
Flat rate unit | 00 00 556

Job time without allowance for / fuel supply
Flat rate unit | 16 99 000

Troubleshooting electrical/electronic system
Flat rate unit I 61 00 009

Metering line
Part I 16 19 7 295 663

1.0

Repair history/customer complaint history

Date of repair	Vehicle mileage	Retailer
01/10/16	167928 km	07825

Job

Considered as a repeat visit. No

Resetting the RDC
Flat rate unit I 36 11 503

Winterräder montieren Sommerräder einlagern
Flat rate unit I 00 00 024

REIFENEINLAGERUNG FÜR EINE SAISON
Part I VS999966666

Local

1

01/10/16	167928 km	07825
----------	-----------	-------

Job

Considered as a repeat visit. No

Vehicle check in course of reception
Flat rate unit I 00 52 054

Job

Considered as a repeat visit. No

Replacing seat cover of rear seat
Flat rate unit I 52 26 901

Removing and installing or replacing side section of backrest on left or right rear seat backrest
Flat rate unit I 52 26 508

Polishing car
Flat rate unit I 00 11 379

Cleaning inside of car
Flat rate unit I 00 11 315

Performing vehicle test
Flat rate unit I 00 00 556

Programming/encoding control unit(s)
Flat rate unit I 61 00 730

Job time without allowance for / electrical system
Flat rate unit I 61 99 000

Checking function of Car Communication Computer
Flat rate unit I 65 83 005

Replacing trim panel for instrument panel
Flat rate unit | 51 45 531

Removing and installing trim panel for instrument panel
Flat rate unit | 51 45 529

Removing and installing front controller
Flat rate unit | 61 31 695

Remove and install HU-H
Flat rate unit | 65 12 815

Removing and installing trim cover for gear selector lever
Flat rate unit | 61 31 836

Replacing centre fresh air outlet
Flat rate unit | 64 22 667

Removing and installing headliner
Flat rate unit | 51 44 502

Removing and installing or replacing all carpets
Flat rate unit | 51 47 950

Job time without allowance for / body
Flat rate unit | 41 99 000

Removing and installing/replacing the weather strip on the outside left or right rear door
Flat rate unit | 51 22 800

Removing and installing/replacing the sound insulation at the rear left or right door
Flat rate unit | 51 48 070

Replacing door window fixed in left or right rear window frame
Flat rate unit | 51 34 691

Removing and installing or replacing plate on window frame of left or right rear door
Flat rate unit | 51 34 925

Removing and installing or replacing both switches on sports steering wheel
Flat rate unit | 61 31 729

Removing and installing or replacing airbag unit
Flat rate unit | 32 34 530

Repair kit, socket housing 1
Part | 61 13 2 359 994

Repair kit f gear selector switch cover 1
Part | 61 31 9 346 827

Bushing contact 2
Part | 61 13 0 006 663

Controller 1
Part | 65 82 9 350 723

Envelope f optical waveguide 10
Part | 61 13 8 387 214

Bushing contact 2
Part | 61 13 0 005 197

Covering cap Part I 61 13 8 387 204	1
Covering cap Part I 61 13 8 387 206	1
Jack MQS ELA Part I 61 13 8 366 260	12
Protection cap Part I 61 13 8 384 666	1
Socket housing Part I 61 13 8 384 550	10
Jack MQS ELA Part I 61 13 1 393 704	20
Trim f.instr.panel Amer.oak front pass. Part I 51 45 9 284 856	1
Instrument cluster Part I 62 10 6 844 042	1
Instrument panel leather Head-Up Display Part I 51 45 9 298 902	1
Sound insulation set Part I 51 48 9 258 252	1
Leather cover for basic seat Part I 52 20 7 353 356	1
Side finisher, leather, left Part I 52 20 7 358 265	1
Exch. headunit high Part I 65 12 9 325 975	1
Repair kit, radio and A/C control panel Part I 64 11 9 388 808	1
Oval-head screw with washer Part I 07 14 9 185 673	2
Central information display Part I 65 50 9 347 878	1
Fillister head screw Part I 07 14 9 129 258	2
Switch, multifct.steering wheel, M-Sport Part I 61 31 7 849 412	1
Rep.module aerial line SDARS Part I 61 11 9 338 193	1
Repair kit, plug, with stops Part I 61 11 9 241 656	1
Rep.module aerial lines FM1/ FM2 Part I 61 11 6 821 952	1

Rep.module aerial GPS Part I 61 11 9 338 192	4
Rep.module basic version head unit Part I 61 11 9 369 643	1
Rep.module telephone Part I 61 11 9 379 320	1
Rep.module Teleservices Part I 61 11 9 338 182	1
Connecting line Headunit High - CID Part I 61 11 9 338 018	1
Optical waveguide Part I 61 12 0 142 318	1
Fibre-optic conductor, left Part I 63 31 9 289 942	1
Fuse Mini, brown Part I 61 13 6 917 402	1
Clip with sealing washer, beige Part I 51 47 7 117 532	2
Optical waveguide, socket contact Part I 61 13 6 906 554	6
Optical waveguide, pin contact Part I 61 13 6 905 233	6
Envelope f optical waveguide Part I 61 13 6 919 111	2
Optical waveguide, connector Part I 61 13 6 906 535	2
Cable tie Part I 61 13 1 367 599	40
Cable tie Part I 61 13 1 377 134	30
Rep. module, head-up display Part I 61 11 9 322 250	1
Trim, seat rail, rear right Part I 52 10 7 348 338	1
Clamp Part I 52 10 1 945 543	55
Clamp Part I 07 14 9 158 807	5
Repair kit, window glass, cold, 1 hour Part I 83 19 2 289 285	1
Butyl cord Terostat 2460 Part I 83 19 0 000 537	0.25

Fillister head screw Part 72 11 9 122 425		1
Clip with sealing ring Part 51 41 8 224 781		4
Fillister head screw Part 07 14 9 129 491		1
Set, shift paddles Part 61 31 9 242 983		1
Airbag module, driver's side Part 32 30 7 845 797		1
Saucer-head screw Part 32 30 6 769 431		2
Control unit, steering wheel electronics Part 61 31 7 849 446		1
Insert, door window glass, left Part 51 35 7 387 419		1
Fixed door window, green, left Part 51 35 7 289 683		1
SOUND INSULATING DOOR REAR LEFT Part 51 48 7 343 215		1
Channel cover, outer, door, rear left Part 51 22 7 289 643		1
M Sports steering wheel leather Part 32 30 7 851 498		1
Cover, steering wheel, rear Part 32 30 7 847 459		1
Decorative trim, steering wheel Part 32 30 7 847 440		1
Hex Bolt Part 32 30 6 795 924		1
connecting line, steering wheel Part 32 30 7 848 335		1
Acoustic foam part Part 32 30 7 850 621		1
Set of screws Part 32 30 7 848 333		1
AT-PFAND Part VS99990000555	Local	1000
Job		
Considered as a repeat visit.	No	
Washing car body Flat rate unit 00 11 319		

Job

Considered as a repeat visit.	No
-------------------------------	----

Job

Considered as a repeat visit.	No
-------------------------------	----

Job

Considered as a repeat visit.	No
-------------------------------	----

09/06/16	145557 km	07825
----------	-----------	-------

Job

Considered as a repeat visit.	No
-------------------------------	----

Service consultation at vehicle with Service Ticket
Flat rate unit I 00 52 052

Job

Considered as a repeat visit.	No
-------------------------------	----

Service - standard scope
Flat rate unit I 00 00 105

Service, vehicle check
Flat rate unit I 00 00 624

Job

Considered as a repeat visit.	No
-------------------------------	----

Additional job, service - recirculating air filter
Flat rate unit I 00 00 617

Microfilter, recirculated air Part I 64 31 9 194 098	1
---	---

Job

Considered as a repeat visit.	No
-------------------------------	----

Engine oil service
Flat rate unit I 00 00 610

BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	6.5
--	-----

Set oil-filter element Part I 11 42 8 507 683	1
--	---

Job

Considered as a repeat visit.	No
-------------------------------	----

Microfilter service
Flat rate unit I 00 00 616

Pollen-filter housing cleaner Part I 83 19 2 180 509	1
---	---

Set, microfilter/carbon canister Part I 64 11 9 248 294	1
--	---

Job

Considered as a repeat visit.	No
-------------------------------	----

Sommerräder quertauschen Vorderachse/Hinterachse
Flat rate unit I 00 00 025

Job

Considered as a repeat visit.	No
-------------------------------	----

Fahrzeug aussaug./Frontscheibe reinigen ohne Berechnung
Flat rate unit I 00 11 317

Job

Considered as a repeat visit.	No
-------------------------------	----

Job

Considered as a repeat visit.	No
-------------------------------	----

12/04/16	134000 km	07825
----------	-----------	-------

Job

Considered as a repeat visit.	No
-------------------------------	----

Job time without allowance for / brakes
Flat rate unit I 34 99 000

Perform brake test on test stand
Flat rate unit I 34 00 009

Service consultation at vehicle with Service Ticket
Flat rate unit I 00 52 052

Removing and installing or replacing both front brake discs
Flat rate unit I 34 11 220

Balancing front and rear wheels stationary
Flat rate unit I 36 10 568

Kunde beanstandet folgende Mängel: Vibrationen beim Bremsen ab ca. 120 km/h
Flat rate unit I 00 00 001

Wheel bolt black	1
Part I 36 13 6 781 151	

Brake disc, ventilated	2
Part I 34 11 6 868 939	

Repair kit, brake pads asbestos-free	1
Part I 34 11 6 852 253	

Job

Considered as a repeat visit.	No
-------------------------------	----

Fahrzeug aussaug./Frontscheibe reinigen ohne Berechnung
Flat rate unit I 00 11 317

Job

Considered as a repeat visit. No

Ersatzfahrzeug 34000656001
Flat rate unit | 99 99 999

Technischer Support kontaktiert/Fall-Nr:6258510 8
Flat rate unit | 99 99 999

12/04/16 122773 km 07825

Job

Considered as a repeat visit. No

Service consultation at vehicle with Service Ticket
Flat rate unit | 00 52 052

Job

Considered as a repeat visit. No

Kunde beanstandet folgende Mängel:beim Bremsvorgang bei ca.120KmH zieht
das Fzg stark
Flat rate unit | 00 00 001

Job

Considered as a repeat visit. No

Removing and installing or replacing both front brake discs
Flat rate unit | 34 11 220

Repair kit, brake pads asbestos-free 1
Part | 34 11 6 852 253

Inner hex bolt 2
Part | 34 21 1 161 806

Brake pad wear sensor, front left 1
Part | 34 35 6 792 567

Clip 2
Part | 34 11 6 798 126

Brake-pad paste 2
Part | 83 19 2 158 851

Brake disc, ventilated 2
Part | 34 11 6 868 939

Job

Considered as a repeat visit. No

Washing car body
Flat rate unit | 00 11 319

Fahrzeug aussaug./Frontscheibe reinigen ohne Berechnung
Flat rate unit | 00 11 317

12/04/16 122773 km 07825

Job

Considered as a repeat visit. No

Service consultation at vehicle with Service Ticket
Flat rate unit | 00 52 052

Job

Considered as a repeat visit. No

Kunde beanstandet folgende Mängel:beim Bremsvorgang bei ca.120KmH zieht
das Fzg stark
Flat rate unit | 00 00 001

Job

Considered as a repeat visit. No

Removing and installing or replacing both front brake discs
Flat rate unit | 34 11 220

Clip -2
Part | 34 11 6 798 126

Repair kit, brake pads asbestos-free -1
Part | 34 11 6 852 253

Brake-pad paste -2
Part | 83 19 2 158 851

Brake pad wear sensor, front left -1
Part | 34 35 6 792 567

Brake disc, ventilated -2
Part | 34 11 6 868 939

Inner hex bolt -2
Part | 34 21 1 161 806

Job

Considered as a repeat visit. No

Washing car body
Flat rate unit | 00 11 319

Fahrzeug aussaug./Frontscheibe reinigen ohne Berechnung
Flat rate unit | 00 11 317

12/04/16 19240 km 07825

Job

Description Front axle brakes - cyclical vibration from steering wheel Poor running characteristics / friction

Job time without allowance for / brakes
Flat rate unit | 34 99 000

Perform brake test on test stand
Flat rate unit | 34 00 009

Removing and installing or replacing both front brake discs
Flat rate unit | 34 11 220

Balancing front and rear wheels stationary
Flat rate unit | 36 10 568

Removing and installing or replacing both front brake discs
Flat rate unit | 34 11 609

Repair kit, brake pads asbestos-free 1.0
Part | 34 11 6 852 253

Wheel bolt black 1.0
Part | 36 13 6 781 151

Brake disc, ventilated 2.0
Part | 34 11 6 868 939

23/03/16 131338 km 07825

Job

Considered as a repeat visit. No

Initialising tyre failure indicator
Flat rate unit | 36 11 500

Replacing two runflat tyres
Flat rate unit | 36 12 055

Sommerräder montieren Winterräder einlagern
Flat rate unit | 00 00 025

Pirelli Scorpion Verde r-f 2
Part | 85 45 2 593 810

ZINKGEWICHTE Local 4
Part | FT99998100666

REIFENEINLAGERUNG FÜR EINE SAISON Local 1
Part | VS99996666667

Job

Considered as a repeat visit. No

Fahrzeug aussaug./Frontscheibe reinigen ohne Berechnung
Flat rate unit | 00 11 317

16/02/16 8013 km 07825

Job

Description Front axle brakes - cyclical vibration from steering wheel Poor running characteristics / friction

Removing and installing or replacing both front brake discs
Flat rate unit | 34 11 609

Perform brake test on test stand
Flat rate unit | 34 00 009

Inner hex bolt 2.0
Part | 34 21 1 161 806

Brake disc, ventilated 2.0
Part | 34 11 6 868 939

Repair kit, brake pads asbestos-free Part I 34 11 6 852 253	1.0
--	-----

Brake pad wear sensor, front left Part I 34 35 6 792 567	1.0
---	-----

12/02/16 122773 km 07825

Job

Considered as a repeat visit.	No
-------------------------------	----

Service consultation at vehicle with Service Ticket
Flat rate unit I 00 52 052

Job

Original customer statement	Beim Bremsvorgang bei ca. 120Kmh zieht das Fzg. stark nach rechts und das Lenkrad flattert
-----------------------------	--

Considered as a repeat visit.	No
-------------------------------	----

Kunde beanstandet folgende Mängel:beim Bremsvorgang bei ca.120Kmh zieht das Fzg stark
Flat rate unit I 00 00 001

Job

Considered as a repeat visit.	No
-------------------------------	----

Removing and installing or replacing both front brake discs
Flat rate unit I 34 11 220

Clip Part I 34 11 6 798 126	2
--------------------------------	---

Brake pad wear sensor, front left Part I 34 35 6 792 567	1
---	---

Brake-pad paste Part I 83 19 2 158 851	2
---	---

Brake disc, ventilated Part I 34 11 6 868 939	2
--	---

Inner hex bolt Part I 34 21 1 161 806	2
--	---

Repair kit, brake pads asbestos-free Part I 34 11 6 852 253	1
--	---

Job

Considered as a repeat visit.	No
-------------------------------	----

Washing car body
Flat rate unit I 00 11 319

Fahrzeug aussaug./Frontscheibe reinigen ohne Berechnung
Flat rate unit I 00 11 317

Job

Considered as a repeat visit.	No
-------------------------------	----

Considered as a repeat visit.	No	
Engine oil service Flat rate unit I 00 00 610		
BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950		6.5
Set oil-filter element Part I 11 42 8 507 683		1
Job		
Considered as a repeat visit.	No	
Service fuel filter Flat rate unit I 00 00 604		
Fuel filter cartridge Part I 13 32 7 811 227		1
Hose clamp Part I 07 12 9 952 104		2
Job		
Considered as a repeat visit.	No	
Service - air filter element Flat rate unit I 00 00 602		
Air filter element Part I 13 71 8 518 111		1
Job		
Considered as a repeat visit.	No	
Microfilter service Flat rate unit I 00 00 616		
Set, microfilter/carbon canister Part I 64 11 9 248 294		1
Pollen-filter housing cleaner Part I 83 19 2 180 509		1
Job		
Considered as a repeat visit.	No	
Additional job, service - recirculating air filter Flat rate unit I 00 00 617		
Microfilter, recirculated air Part I 64 31 9 194 098		1
Job		
Considered as a repeat visit.	No	
Job time without allowance for / electrical system Flat rate unit I 61 99 000		

Battery

Part I 66 12 6 912 985

1

Job

Considered as a repeat visit.

No

Fahrzeug aussaug./Frontscheibe reinigen ohne Berechnung

Flat rate unit I 00 11 317

08/09/15

88679 km

07825

Job

Considered as a repeat visit.

No

Service consultation at vehicle with Service Ticket

Flat rate unit I 00 52 052

Job

Considered as a repeat visit.

No

Service - standard scope

Flat rate unit I 00 00 105

Engine oil service

Flat rate unit I 00 00 610

Set oil-filter element

Part I 11 42 8 507 683

1

CASTROL 0W-30 LL04 EDGE

Part I FT999984000

Local

6.5

Job

Considered as a repeat visit.

No

Service, vehicle check

Flat rate unit I 00 00 624

Diesel exhaust fluid AdBlue

Part I 83 19 2 295 606

0.5

Job

Considered as a repeat visit.

No

Microfilter service

Flat rate unit I 00 00 616

Pollen-filter housing cleaner

Part I 83 19 2 180 509

1

Set, microfilter/carbon canister

Part I 64 11 9 248 294

1

Job

Considered as a repeat visit.

No

Additional job, service - recirculating air filter

Flat rate unit I 00 00 617

Microfilter, recirculated air
Part I 64 31 9 194 098 1

Job

Considered as a repeat visit. No

Washing car body
Flat rate unit I 00 11 319

Fahrzeug aussaug./Frontscheibe reinigen ohne Berechnung
Flat rate unit I 00 11 317

31/08/15 94859 km 07825

Job

Considered as a repeat visit. No

Vehicle check in course of reception
Flat rate unit I 00 52 054

Job

Considered as a repeat visit. No

Replacing four runflat tyres
Flat rate unit I 36 12 076

Dunlop Grandtrek WT M3 ROF 4
Part I 85 45 2 535 059

GUMMIVENTIL Local 4
Part I FT999999993

ZINKGEWICHTE Local 8
Part I FT999981006

Job

Considered as a repeat visit. No

Initialising tyre failure indicator
Flat rate unit I 36 11 500

Winterräder montieren Sommerräder einlagern
Flat rate unit I 00 00 024

REIFENEINLAGERUNG FÜR EINE SAISON Local 1
Part I VS999966666

Job

Considered as a repeat visit. No

Winter season service
Flat rate unit I 00 12 250

Windshield washer antifreeze 1
Part I 83 12 2 298 206

Job

Considered as a repeat visit. No

Fahrzeug aussaug./Frontscheibe reinigen ohne Berechnung
Flat rate unit I 00 11 317

17/04/15 67828 km 07825

Job

Considered as a repeat visit. No

Service consultation at vehicle with Service Ticket
Flat rate unit I 00 52 052

Job

Considered as a repeat visit. No

Initialising tyre failure indicator
Flat rate unit I 36 11 500

Sommerräder montieren Winterräder einlagern
Flat rate unit I 00 00 025

REIFENEINLAGERUNG FÜR EINE SAISON
Part I VS9999666667

Local

1

Job

Considered as a repeat visit. No

Fahrzeug aussaug./Frontscheibe reinigen ohne Berechnung
Flat rate unit I 00 11 317

16/02/15 59568 km 07825

Job

Original customer statement *Prüfplan bearbeitet

Original customer statement *Heizung Dosierleitung Adblue geprüft

Original customer statement *Heizung defekt

Considered as a repeat visit. No

Job time without allowance for / fuel supply
Flat rate unit I 16 99 000

Troubleshooting electrical/electronic system
Flat rate unit I 61 00 009

Performing vehicle test
Flat rate unit I 00 00 556

Metering line
Part I 16 19 7 295 663

1

16/02/15 59568 km 07825

Job

Considered as a repeat visit. No

Service consultation with customer at vehicle without service ticket
Flat rate unit I 00 52 053

Service - standard scope
Flat rate unit | 00 00 105

Job

Considered as a repeat visit. No

Service, vehicle check
Flat rate unit | 00 00 624

Job

Considered as a repeat visit. No

Engine oil service
Flat rate unit | 00 00 610

Set oil-filter element 1
Part | 11 42 8 507 683

CASTROL 0W-30 LL04 EDGE Local 6.5
Part | FT99998400000

Job

Considered as a repeat visit. No

Service fuel filter
Flat rate unit | 00 00 604

Fuel filter cartridge 1
Part | 13 32 7 811 227

Hose clamp 2
Part | 07 12 9 952 104

Job

Considered as a repeat visit. No

Service - air filter element
Flat rate unit | 00 00 602

Air filter element 1
Part | 13 71 8 518 111

Job

Considered as a repeat visit. No

Microfilter service
Flat rate unit | 00 00 616

Set, microfilter/carbon canister 1
Part | 64 11 9 248 294

Pollen-filter housing cleaner 1
Part | 83 19 2 180 509

Job

Considered as a repeat visit. No

Additional job, service - recirculating air filter
Flat rate unit | 00 00 617

Microfilter, recirculated air
Part I 64 31 9 194 098 1

Job

Considered as a repeat visit. No

Fahrzeug aussaug./Frontscheibe reinigen ohne Berechnung
Flat rate unit I 00 11 317

08/12/14 48795 km 07825

Job

Original customer statement none

Considered as a repeat visit. No

Vehicle check in course of reception
Flat rate unit I 00 52 054

Job

Original customer statement none

Considered as a repeat visit. No

Calibrate KAFAS camera
Flat rate unit I 66 51 526

Initializing rain-light sensor
Flat rate unit I 61 35 679

Replacing windshield
Flat rate unit I 51 31 011

Rubber buffer 7
Part I 51 31 1 925 433

Clip 12
Part I 51 13 7 361 268

Cover, windshield, top 1
Part I 51 31 7 292 394

Windscreen, green, rain sensor / HUD 1
Part I 51 31 7 292 402

Sensor rain/light/solar/misting over HUD 1
Part I 61 35 9 354 225

Spacer, adhesive 4
Part I 51 31 7 186 167

SOUND INSULATION F APRON 1
Part I 51 48 9 143 684

Repair kit, window glass, cold, 1 hour 1
Part I 83 19 2 289 287

Instruction notice, Airbag 1
Part I 71 21 2 122 334

FEINSTAUBPLAKETTE GRÜN
 Part I VS99998000207

Local

1

Job

Original customer statement	none
-----------------------------	------

Considered as a repeat visit.	No
-------------------------------	----

Fahrzeug aussaug./Frontscheibe reinigen ohne Berechnung
 Flat rate unit I 00 11 317

Job

Original customer statement	Hinweis: - Schaltzentrum Lenksäule Hardwarefehler
-----------------------------	---

Original customer statement	- Folgetermin vereinbaren
-----------------------------	---------------------------

Considered as a repeat visit.	No
-------------------------------	----

03/11/14 43506 km 07825

Job

Original customer statement	none
-----------------------------	------

Considered as a repeat visit.	No
-------------------------------	----

Removing and installing or replacing foot board, left or right
 Flat rate unit I 51 71 476

Footboard, sill, right Part I 51 77 7 294 386	1
--	---

Support piece, sill, footboard, right Part I 51 77 7 294 384	1
---	---

Cover, sill, footboard, right Part I 51 77 7 294 380	1
---	---

Insert, side sill, footboard, right Part I 51 77 7 345 096	1
---	---

Expanding rivet, black Part I 51 77 7 171 004	6
--	---

Clip Part I 51 77 7 171 003	10
--------------------------------	----

Clip Part I 51 77 7 171 002	6
--------------------------------	---

03/11/14 43506 km 07825

Job

Original customer statement	none
-----------------------------	------

Considered as a repeat visit.	No
-------------------------------	----

Vehicle check in course of reception
 Flat rate unit I 00 52 054

Job

Original customer statement none

Considered as a repeat visit. No

Initialising tyre failure indicator
Flat rate unit | 36 11 500

Winterräder montieren Sommerräder einlagern
Flat rate unit | 00 00 024

REIFENEINLAGERUNG FÜR EINE SAISON Local 1
Part | VS99996666667

Job

Original customer statement none

Considered as a repeat visit. No

Fahrzeug aussaug./Frontscheibe reinigen ohne Berechnung
Flat rate unit | 00 11 317

18/08/14 29047 km 07825

Job

Considered as a repeat visit. No

Vehicle check in course of reception
Flat rate unit | 00 52 054

Job

Considered as a repeat visit. No

Engine oil service
Flat rate unit | 00 00 610

Service - standard scope
Flat rate unit | 00 00 105

Set oil-filter element 1
Part | 11 42 8 507 683

CASTROL 0W-30 LL04 EDGE Local 6.5
Part | FT99998400000

Job

Considered as a repeat visit. No

Microfilter service
Flat rate unit | 00 00 616

Set, microfilter/carbon canister 1
Part | 64 11 9 248 294

Pollen-filter housing cleaner 1
Part | 83 19 2 180 509

Job

Considered as a repeat visit. No

Additional job, service - recirculating air filter
Flat rate unit | 00 00 617

Microfilter, recirculated air 1
Part | 64 31 9 194 098

Job

Considered as a repeat visit. No

Fahrzeug aussaug./Frontscheibe reinigen ohne Berechnung
Flat rate unit | 00 11 317

20/02/14 0 km 07825

Job

Considered as a repeat visit. No

Job time without allowance for / wheels
Flat rate unit | 36 99 000

Checking function of navigation system
Flat rate unit | 65 90 000

Free pre-delivery inspection
Flat rate unit | 00 00 009

Washing car body and cleaning inside of car
Flat rate unit | 00 11 329

Job time without allowance for / radio and special equipment
Flat rate unit | 65 99 000

Kunde: Pro Works.... Verk.: Hr. Hein
Flat rate unit | 00 00 015

!!! unknown BMW-Id 0000011 Farbe: imperialblau..... !!!
Flat rate unit | 00 00 011

10 Liter Benzin o. Diesel
Flat rate unit | 00 00 021

Fillister head self-tapping screw 8
Part | 07 14 3 448 498

Covering cap 4
Part | 51 18 1 813 017

Covering cap 4
Part | 51 18 7 060 798

Windshield washer antifreeze 2.5
Part | 83 12 2 298 206